




STATE OF THE ART FOR O-RINGS: STANDARDIZATION - TESTING - MATERIALS


STAND DER TECHNIK BEI O-RINGEN: NORMUNG - PRÜFTECHNIK - WERKSTOFFE

WHAT IS A GOOD SEALING FUNCTION









REQUIREMENTS FOR A GOOD SEALING FUNCTION

GLAND DESIGN

- Enough deformation even at worst case tolerances
- Good surfaces
- No sharp edged surfaces
- No too big gaps


O-RING PROPERTIES

- Keeping the dimensional tolerances
- Good recipe and controlled vulcanization process
- No critical surface defects

ASSEMBLING

- No dirt on sealing surfaces
- No intermixing of compounds
- No contact with sharp edges







tensile strenght/ elonga-

tion at break

compression set

TGA/IR-anlysis









STATE OF THE ART FOR O-RINGS: STANDARDIZATION - TESTING - MATERIALS

STAND DER TECHNIK BEI O-RINGEN: NORMUNG – PRÜFTECHNIK – WERKSTOFFE

STATE OF THE ART

STANDARDIZATION

ISO 3601-1 ISO 3601-3

ISO 3601-5

TESTING

Automated visual inspection and measuring

Analytical test
methods for
compound-identification

Safer results by accreditation

MATERIALS

FFKM and FKM with improved cold-flexibility and steam resistance

Enlarged range of cross-section tolerances (ISO 3601-1) and limits for surface imperfections (ISO 3601-3) up to 14,0 mm


Requirements for recipes and for o-ring-properties of NBR, HNBR, EPDM, FKM, VMQ and ACM-materials

Automated visual inspection machines available for o-rings from 0,8 mm inside-diameter to > 1000 mm and from 0,26 mm cross-section to 30 mm including dimensional testing

TGA-analysis indicates the main ingredients of a recipe in regard to weight contents while FTIR-analysis identifies the chemical structure of the polymer and the other ingredients.

ISO/IEC 17025 defines general requirements for the competence of testing and calibration laboratories, accreditation assures conformity

Special FKM-grades for low temperature <-40°C as well FFKM types for improved low temperature (<-30°C) allow a better cold flexibility together with best aging and chemical resistance



Compression Set Requirements for O-Rings

t=24h

NBR S 70

HNBR 75

FKM 70/75/80

EPDM F

 t=24h
 NBR S 70
 HNBR 75
 FKM 70/75/80
 EPDM P 70/80

 Test-Temp. [°C]
 100
 150
 200
 150

 Compression set [%] (min. 2 mm d2)
 35
 40
 25
 30

 Compression set [%] (< 2 mm d2)</td>
 40
 45
 30
 35

